

2010 Honda Odyssey M Fine Spirit		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RB3	DISPLACEMENT 2,354 cc		
YEAR / REG. 2010/11	MILEAGE 175,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. RB3-1120666	DIMENSIONS (L X W X H) 480 × 180 × 155 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Numerous small scratches on the exterior.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H22/11月		メーカー ホンダ		ドア枚数 5	ボディ形状 ステーションワゴン	評価点 R																				
車名 オデッセイ		グレード Mファインスピリット		駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 2400 cc	型式 DBA-RB3	通称 型式	内装 A・B・C																						
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)																							
走行 175,000 km	シフト インパネ	AT																								
外装色 シルバー	カラーNo. ()	エアコン AG・QG・WAG・()	新着品のみ O印 を記入																							
内装色 ()	乗車定員 7 人	PS	PW	AW	サンルーフ	革シート																				
ハンド 左・右	輸入 区分	ディーラー	並行	エアバック	ABS	ナビ																				
セーリング料 13,850 円		預託金	エアバック	ABS	ナビ	TV																				
セールスポイント																										
検査記入欄		修復歴 ○ 無																								
外装小傷多数		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ・ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
		登録No. 月 日 までに名変できる方																								
		車検番号 RB3-1120666																								
FW	トビ	備A	ワレ	外装	小	ホイール	エアロ	シリアル No.																		
内装	ヨコ	シタ	ヤブ	コガ	コガ穴	オーディオ穴	取組	長さ cm																		
							高さ cm	最大積重量 kg																		