

2010 Honda ZEST SPARK W		OVERALL 3	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-JE1	DISPLACEMENT 658 cc		
YEAR / REG. 2010/06	MILEAGE 119,250 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Kei		
CHASSIS NO. JE1-1308370	DIMENSIONS (L X W X H) 340 × 148 × 164 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Exterior has scratches, dents, paint peeling, fading, and discoloration. Compressor is faulty with oil seepage. The power window behind the driver's seat is faulty, and the rear outer handle is damaged. The interior has scuffs, dirt, and scratches. The audio system is missing. The fuel filler cap opening lever cover is missing, the trunk board is damaged, and there is rust on the undercarriage.			

印字位置確認		ホンダ		ボディ版数 5		ボディ部分 軽四		評価点	
H22 / 6月		車名		グレード		駆動方式		3	
		ゼストスパークW				2WD 4WD			
車種	自動車・その他()	排気量	650	型式	CC	DBA-J E1	通称形式	内装	A・B・G
車検	- - 年 - - 月 / (日)	燃料	ガソリン	ディーゼル	()	貴重品等 (保証書・取扱説明書等)			
走行	CIDにマークを記入(万全交換) (成金形) (不換)	エンジン	シャフト	インパネ AT					
走行	[] [] 1 1 9 , 2 5 0 マイル	カラーNo.	()						
外装色	ブラック	カラーNo.	()	AD・GD・WG・C	新着品のみのO印を記入				
内装色	()	内装色	()	乗車人数	4人				
左・右	輸入区分	ディーター	運行	リサイクル料	10,000円・買値				
セールスポイント									
★ユーザー買い取り車両! ETC!									
検査記入欄									
外装キズ凹みハゲヒビあせ、コンプレッサー不良、オイルしみ、PW運転席後部不良、後部アウトウーハンドル破損、内装スレ汚れキズ、オーディオレス、給油口開閉レバーパー欠品、トランクボード破損、足回り錆									
修正箇所 有 (●)									
PW	(点検)	機A	フレ	外装	小	ホイール	エアロ	シリアル	No.
内装	(点検)	シヤ	ヤツル	コグ	コグス	オーヂオス	高圧	車検	車検