

2010 Nissan Elgrand Interior Cleaned! Saga Origin! Rider Black Cloth Seat Specification Half Leather Flip-down Dual Power Slide Door Front/Rear Monitor		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-TE52	DISPLACEMENT 2,488 cc		
YEAR / REG. 2010/11	MILEAGE 119,220 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Minivan		
CHASSIS NO. TE52-007282	DIMENSIONS (L X W X H) 498 × 185 × 182 cm		
SALES POINTS			
Alloy Wheels Leather Seats Back Camera		AUTECH Front Camera Navigation System	
INSPECTOR REPORT			
Interior cleaned. Timing chain engine. Minor scratches and dents on various parts, repaired. Minor scratches on alloy wheels.			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 H22 11月	メーカー 日産 車名 エルグラン	ドア数 5	ボディタイプ ミニバン/ワンボックス	評価点 4
車種 自家用・その他 ()	排気量 2500 cc	型式 DBA-TE52	駆動方式 2WD 4WD	内装 A・B・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 119,220 km	インパネ	CVT	後部座席 ()	後部座席 ()
外装色 パール	カラーNo. (QAB)	エンジン AG・AGC・WAG・ ()	装備品のみ・O印を記入	
16,190円	16,190円	16,190円	16,190円	16,190円
セールスポイント				
キーレスエントリー/A B S/運転席エアバック/助手席エアバック/サイドエアバック/H D Dナビ/フルセグTV/ETC/スマートキー/フルエアロ/H I D・キセノン・ディスプレイ/オートマン/3列シート/D V D再生/ミュージックサーバー/CD/バックカメラ/後席モニター/両側電動スライドドア/ハーフレザーシート/2 0 A W				
検査記入欄				
☆室内クリーニング済み! ☆タイミングチェーン式! 各小A小U・補修 アルミA				
修理履歴				
A キズ B へこみ C 凹み D 傷 E 色あせ F 汚れ G ガラスキズ H 補修 I 錆 J サビ K 腐食 L 交換 M 交換 N 交換 O 交換 P 交換 Q 交換 R 交換 S 交換 T 交換 U 交換 V 交換 W 交換 X 交換 Y 交換 Z 交換				
名義中				
月 日 までに見学できる方				
車検番号 TE52-007282				
車検有効期限				
最大積載量				