

2010 Nissan MARCH 12G		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE K13	DISPLACEMENT 1,198 cc		
YEAR / REG. 2010/09	MILEAGE 19,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gold	BODY TYPE Hatchback		
CHASSIS NO. K13-310819	DIMENSIONS (L X W X H) 378 × 167 × 152 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior small and light scratches. Purchased with an AA rating of 3.5. Upper support replaced (bolt-on). Left C-pillar lower part and left rear wheel arch have bodywork/paint.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H22/9月	メーカー 日産	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 3.5
車種 乗用車	グレード 12G	エンジン 1200cc	変速機 AT	駆動方式 2WD
走行 19,000km	燃料 ガソリン	シフト フロア	エアコン あり	安全装置 ABS・エアバッグ
外装色 シャンパーニュゴールドM	カラーNo. 000	内装色 ブラック	オプション A・B・C	整備品のみ O印を記入
左・右 左	ディーラー ディーラー	走行 8,800円	エンジン E	AW あり
セールスポイント CD/バックカメラ/TC/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/衝突安全ボディ/アイドリングストップ/DVD再生/ミュージックプレイヤー-接続可				
検査記入欄 内装キズ、汚れ シートシレ、シワ 外装キズ、傷 AA等級3.5点仕入れ ネジ止めアップリットポート交換 左Cピラー下端DP 左RタイヤハウスDP				
修復歴 有・無 A キズ U ヘッドライト B キズ・ヘッド C 色あせ・傷 D ガラスキズ W 燃費 S サビ Q 腐食 X 交換 Y 交換 Z 交換 名義中 月 日 までに名義できる方 車体番号 K13-310819				
車体重量 1,198kg				