

ORIGINAL JAPANESE AUCTION SHEET

注意事項：不具合箇所

- ・内装外装仕上げ済み
- ・取説
- ・R7/12タイヤ新品交換済み

検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入

- ・内装スレ、キズ 少

The diagram shows a top-down view of a car chassis. Various components are labeled with codes: A1 (front/rear fenders, side sills, rear quarter panels), B2 (front/rear crossmembers), and C1 (wheels/tires). Dimensions are indicated with brackets and 'mm'.

ドアミラー	キズ	セビ	ウレ