

2010 Suzuki Jimny XG		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ABA-JB23W	DISPLACEMENT 658 cc		
YEAR / REG. 2010/08	MILEAGE 174,037 km		
DOORS 3	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. JB23W-625292	DIMENSIONS (L X W X H) 340 × 148 × 168 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Document delivery takes approximately 10 days after contract. Headliner is yellowed, interior is dirty and torn, and the steering wheel is worn. There is rust inside the engine compartment. Undercarriage has moderate corrosion (C2), and the inner pillar has damage (BU).			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H22/8月	メーカー スズキ	ドア枚数 5	ボディ形状 軽四	評価点 3.5
車種 軽自動車・その他 ()	車名 ジムニー	グレード XG	駆動区分 2WD	
走行 174,037 km	排気量 660 cc	型式 ABA-JB23W	燃料 ガソリン	変速機 MT
外装色 シルバー	カラーNo. ()	エンジン AAG・WAG・()	後日添付品 (保証書・取扱説明書 等)	
内装色 ()	内装 ()	安全装置 ()	装備品のみ O印 を記入	
左・右 ()	輸入 ()	走行 ()	エアコン ()	サンルーフ ()
販売店 ()	ディーラー ()	走行 ()	ナビ ()	キーレス ()
セールスポイント		8,540円・税別		
検査記入欄		修復歴 有・無		
精細送付は成約後10日程度かかります。 天窓リキバミ 室内汚れ、破れ ハンドルバグ エンジンルーム内サビ 下回りC2 ピラーインナーBU		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・傷 G ガラスキズ W 燃費 S サビ Q 腐食 X 交換部 XX 交換部 売却先 月 日 までに名義できる方 車体番号 JB23W-625292 シリアル No. 取組 cm cm cm 最大積載量 Kg		