


2011 BMW 1 SERIES 116i Style		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-1A16	DISPLACEMENT 1,598 cc		
YEAR / REG. 2011/12	MILEAGE 38,990 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. WBA1A12020E947092	DIMENSIONS (L X W X H) 434 × 177 × 144 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Right power folding mirror faulty			

ORIGINAL JAPANESE AUCTION SHEET

H23/12月		BMW		ドア枚数	5	ボディ形状	コンパクトハッチバック	評価点	4																				
車名		1シリーズ		グレード	116iスタイル		駆動区分	2WD 4WD																					
車種	自家用・その他 ()	排気量	1600 cc	型式	DBA-1A16		通称	A・C																					
車検	- - 年 / 月	燃料	ガソリン	ディーゼル	後日選り品 (検査・取付・修理等)																								
走行	口内にマークを記入 (金・交換・点検・点検)	シフト	フロア	AT																									
外装色	ダークブルー	カラーNo.	()		新着品のみ O印 を記入																								
内装色	()	乗車定員	人		サンルーフ 革シート																								
ハンド	左・右	輸入区分	デ	走行	19,570円	エンジン	AT	TV	モ																				
セールスポイント																													
★純正ナビ★Bluetooth★プッシュスタート★純正16インチAW★オートライト★CD & DVD再生★Mサーバー★AUX★USB★ステアスイッチ★HID★ASTOP★MTモード付★ETC★ターボ★ヘッドライトウォッシャー★スベアキー★					修復歴 有・無																								
検査記入欄					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
右電格ミラー不良					登録No. 月 日 までに名変できる方																								
					車検番号 WBA1A12020E947092																								
FW	トピ石	備A	フレ	外装	小	ホイル	エアロ	シリアル No.																					
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	重量	最大積重量																				