

2011 BMW_Mini BMW Mini Crossover Cooper S		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-ZC16	DISPLACEMENT 1,598 cc		
YEAR / REG. 2011/08	MILEAGE 77,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE SUV		
CHASSIS NO. WMWZC32080WM21312	DIMENSIONS (L X W X H) 412 × 179 × 155 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Minor glass chip, interior dirty, seat wear, steering wheel scuff, minor scratches and dents, paint fade, alloy wheel scratches, door trim scratches, mirror scratches, and general fading.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23/8月	メーカー MINI 車名 MINI	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4
車種 自家用・その他 ()	排気量 1600 CC	型式 DBA-ZC16	駆動方式 2WD 4WD	内装 A・B
車検 8年9月	燃料 ガソリン ハイブリッド ()	ディーゼル ()	検定通り品 (保証書・取扱説明書 等)	
走行 77,000 km	シフト フロア 6 AT	装備品のみ ORP を記入		
外装色 レッドブラック	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ ORP を記入	
()	内装色 ()	乗車定員 5人	サンルーフ	革シート
左・右 デモ・走行	18,870円・預託金	エアバック	ナビ	TV
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/H I D・キセノン・ディスチャージ/横滑り防止装置 (E S C) /C D /M T モード付き				
検査記入欄				
ガラス トビ A ルーム内汚れ シートへたり ハンドルすれ有 小キズ有へこみ有 P アセ有 AWキズドリムキズ ミラーキズ アセ				
名義中				
月 日 までにも受できる方				
WMWZC32080WM21312				
FW	トビ石	傷A	フレ	外装
内装	ヨゴレ	シミ	ヤブレ	コゲ
小	A・U	A・曲	A・フレ	エアロ
ホイール	スレ	オーディオ	スレ	車輪
長さ	cm	高さ	cm	最大積載量
Kg				