

|                                                                                                                                                                                     |                                              |                                    |          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|------------------------------------|----------|
| 2011 CHRYSLERJEEP JEEP Cherokee Sports                                                                                                                                              |                                              | OVERALL                            |          |
|                                                                                                                                                                                     |                                              | 3                                  |          |
|                                                                                                                                                                                     |                                              | EXTERIOR                           | INTERIOR |
|                                                                                                                                                                                     |                                              | -                                  | -        |
| MODEL CODE<br>ABA-KK37                                                                                                                                                              | DISPLACEMENT<br>3,700 cc                     |                                    |          |
| YEAR / REG.<br>2011/09                                                                                                                                                              | MILEAGE<br>76,325 km                         |                                    |          |
| DOORS<br>5                                                                                                                                                                          | SEATS<br>5                                   |                                    |          |
| DRIVETRAIN<br>4WD                                                                                                                                                                   | TRANSMISSION<br>AT                           |                                    |          |
| FUEL<br>Petrol                                                                                                                                                                      | STEERING<br>Right                            |                                    |          |
| EXTERIOR COLOR<br>Other                                                                                                                                                             | BODY TYPE<br>SUV                             |                                    |          |
| CHASSIS NO.<br>1J4P42GK7BW550313                                                                                                                                                    | DIMENSIONS (L X W X H)<br>450 × 183 × 182 cm |                                    |          |
| SALES POINTS                                                                                                                                                                        |                                              |                                    |          |
| Alloy Wheels<br>Side Camera                                                                                                                                                         |                                              | Leather Seats<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                                                                    |                                              |                                    |          |
| Underbody oil seepage, check engine light on, oil leaks, minor trim wear, seat scuffs and wrinkles, steering wheel wear, headliner scuffs and dirt, headlights yellowed and cloudy. |                                              |                                    |          |

[illegible]