


2011 Daihatsu Mira 5D 660 L		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-L275S	DISPLACEMENT 658 cc		
YEAR / REG. 2011/03	MILEAGE 70,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. L275S-2110877	DIMENSIONS (L X W X H) 340 × 148 × 153 cm		
INSPECTOR REPORT			
Seat half cover, A/W scratches, minor damage B, P fading, minor scratches. Dents and P fading.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23 3月		メーカー ダイハツ		ドア枚数 5		ボディ形状 コンパクト/ハッチバック		評価点 4																					
車名 ミラ		グレード 660 L 5速マニュアル		駆動区分 2WD 4WD																									
車歴 自家用・その他 ()	排気量 660 CC	型式 DBA-L275S	通称 型式	内装 A・B・C																									
車検 - 年 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)																										
走行 70,000 マイル		シフト フロア 5 MT																											
外装色 シルバー	カラーNo. ()	エアコン A・A・C・W・A・C・ ()	装備品のみ O印 を記入																										
内装色 ()	乗車定員 4 人	エアロ	AW	サンルーフ	革シート																								
ハンドル 左・右	輸入 区分	ディーラー	並行	リサイクル料 8,640 円	預託金	エアロパック	ABS	ナビ	TV																				
セールスポイント キーレスエントリー/運転席エアバック/助手席エアバック/CD																													
検査記入欄 シートハーフカバー AWキズ 小傷B Pアセ有 小キズ有 へこみ有 Pアセ有			修復歴 有 () <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ/サレ</td><td>B</td><td>キズ/ヘコミ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td> </tr> </table>							A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済																				
			登録No. _____ 月 _____ 日 までに名変できる方 車体番号 L275S-2110877																										
FW	トビ石	傷A	フレ	外装	小 A・U	ホイール A・曲	エアロ A・フレ	シリアル No.																					
内装	ヨゴレ	シミ	ヤブレ	コゲ	コゲ穴	オーディオ穴	スレ	長さ cm	幅 cm																				
								高さ cm	最大積載量 Kg																				