


2011 Honda CR-Z 1.5 Alpha		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-ZF1	DISPLACEMENT 1,496 cc		
YEAR / REG. 2011/03	MILEAGE 59,310 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Coupe		
CHASSIS NO. ZF1-1025792	DIMENSIONS (L X W X H) 408 × 174 × 140 cm		
SALES POINTS			
Alloy Wheels Navigation System		Cruise Control	
INSPECTOR REPORT			
Front glass: Scratches, stone chips, cracks, repair marks, replacement required. Interior: Scratches, dirt, burns, holes, scuffs, tears, rips.			

ORIGINAL JAPANESE AUCTION SHEET

 (T1) 202607 08116	初度登録年月 平成23年3月	車名・グレード CR-Z α	2WD 4WD	評価点 (4)					
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DAA-ZF1	排気量 1500 CC	ドア 3 形状 CP	定員 4人 積載 kg					
車歴 自家用	シフト CVT	セールスポイント (正常に機能するものに限りです) キーレススマートキー・ETC・バックモニター HIDヘッドライト	外装 B	内装 B					
車検 年 月 (日)	冷房 AAC	装備品 (純正品に限り○をつけてください) PS PW ABS AEB AW SR 4D TV カワ							
走行 5万9千310 km	燃料 ガソリン	新車保証書 有・無							
色 グリーン	色替 BG57P								
R券 12,220 円									
注意事項申告欄									
フロントガラス 内装	キズ・飛石・ヒビ割・リペア跡・X要 キズ・汚レ・コゲ・穴・スレ・キレ・破レ								
車台番号 1025792									
登録番号									



A1 A1 A1 A1
A3 A2
A2
スベア

A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済
型式指定番号 登録区分番号
車検取得年月 備考
備考