

2011 Honda CR-Z Alpha		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-ZF1	DISPLACEMENT 1,496 cc		
YEAR / REG. 2011/06	MILEAGE 77,000 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Coupe		
CHASSIS NO. ZF1-1027115	DIMENSIONS (L X W X H) 408 × 174 × 140 cm		
SALES POINTS			
Alloy Wheels Back Camera		Cruise Control Navigation System	
INSPECTOR REPORT			
Minor scratches and dimples on interior and exterior, front support dent.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23/6月	メーカー ホンダ	ドア枚数 3	ボディ形状 クーペ	評価値 3.5
車名 C R - Z	グレード a	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 1500 cc	型式 DAA-ZF1	通称 A・B・C	内装 A・B・C
年 -	月 -	日 -	燃料 ハイブリッド ()	後付選り品 (保証書・取扱説明書 等)
走行 77,000 km	フロア 6 MT	エアコン	装備品のみ O印 を記入	
外装色 クロ	カラーNo. ()	エアコン A・AAG・WAG・()	サンルーフ	革シート
内装色 ()	車庫定員 人	リサイクル料 12,220円	ナビ	TV
左・前 ディーラー・走行	リサイクル料 12,220円	ナビ	TV	モーター
セールスポイント				
☆6速ミッション ☆無限グリル ☆フジツボマフラー ☆ホワイトレザースタートカバー ☆モジュールアルミホイール				
検査記入欄				
内外装小傷エグボ Fサポートヘコみ				
A2 P117 W2 P117 A3 A2				
修復歴 有・無				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 XX 交換済				
登録No. 月 日 までに変更できる方				
車体番号 ZF1-1027115				
FW () Wレ 外装 小 () ホイル エアロ シリアル No. ()				
内装 () シヤ ヤブレ コガ コガス オーディオ ()				
重量 cm 長さ cm 高さ cm 最大積重量 kg				