

2011 Honda CR-Z Alpha Black Label		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-ZF1	DISPLACEMENT 1,496 cc		
YEAR / REG. 2011/11	MILEAGE 127,450 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Coupe		
CHASSIS NO. ZF1-1101603	DIMENSIONS (L X W X H) 408 × 174 × 140 cm		
SALES POINTS			
Alloy Wheels Back Camera		Cruise Control Navigation System	
INSPECTOR REPORT			
Seat edge wear			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23/11月		メーカー ホンダ		ドア枚数 3	ボディ形状 クーペ	駆動方式 2WD	グレード αブラックレーベル	年式区分 4																				
車種 自家用・その他 ()		排気量 1500 CC	型式 DAA-ZF1	通称 α	内装 A・B・C																							
車検 -年-月-日		燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書等)																								
走行 127,450 km		フロア	CVT																									
外装色 ダークブルー・メタリック		カラーNo.	エアコン	装備品のみ O印 を記入																								
()		内装色 ブラック	乗車定員 4人	EP	PM	AM	サンルーフ	革シート																				
左・前・後 左・前・後		輸入区分 ディーラー	走行 12,220円	エブリック	ABS	ESP	IV	モス																				
セールスポイント																												
検査記入欄				修復歴 有・無																								
シートフチヘタリ				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/ヘコ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/ヘコ	P	色あせ/ボケ	G	ガラスキズ																			
W	補修跡	S	サビ	C	腐食	X	交換部	XX	交換済																			
				登録No. 月 日 までに変更できる方																								
				車体番号 ZF1-1101603																								
FW トビ石 傷A ワレ 外装 小 大				シリアル No.																								
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ				車種 長さ 幅 高さ 最大積載量 Kg																								