

2011 LandRover RANGEROVER Sport 5.0 V8		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LS5N	DISPLACEMENT 4,999 cc		
YEAR / REG. 2011/08	MILEAGE 72,200 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE SUV		
CHASSIS NO. SALLSJAD3BA281146	DIMENSIONS (L X W X H) 480 × 193 × 181 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front)		Leather Seats Navigation System	
INSPECTOR REPORT			
Rear headliner sag. Scuffs on seats and steering wheel. Wheel scratches. Minor scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23/8月	メーカー ランドローバー	ドア枚数 5	ボディ形状 SUV/クワカン	年価 4
車名 レンジローバースポーツ	グレード 5.0 V8	駆動区分 2WD	4WD	
車種 自家用・その他()	排気量 5000 CC	型式 LS5N	通称 A・B・C	
車検 8年11月/抹消	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書等)	
走行 72,200 km	フロア 6 AT	エアコン		
外装色 シルバー	カラーNo. ()	エアコン A・A・G・W・G・()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ	有	
左・前・後 左・前・後	走行 18,730円	預託金	エブリック	有
セールスポイント				
本革シート/パワーシート/CD/バックカメラ/ETC/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/フルセグTV/4WD/オートクルーズコントロール/シートヒーター/サイドカメラ				
検査記入欄				
天張り後部ウキシート、ハンドルすれホイールキズ小傷、小凹み				
修理歴				
有				
A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修部 S サビ C 腐食 X 交換部 XX 交換済				
登録No. 月 日 名義中				
車体番号 SALLSJAD3BA281146				
FW トビ石 傷A フレ 外装 小 A・U A・曲 A・フレ シリアル No.				
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ				
車種 長さ cm 幅 cm 高さ cm 最大積重量 kg				