

| 2011 SUBARU Legacy B4 2.5i EyeSight                                                                                                                                                                                                                                       |                                              | OVERALL                 |          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------------|----------|
|                                                                                                                                                                                                                                                                           |                                              | EXTERIOR                | INTERIOR |
|                                                                                                                                                                                                                                                                           |                                              | -                       | -        |
| MODEL CODE<br>BM9                                                                                                                                                                                                                                                         | DISPLACEMENT<br>2,457 cc                     |                         |          |
| YEAR / REG.<br>2011/03                                                                                                                                                                                                                                                    | MILEAGE<br>94,367 km                         |                         |          |
| DOORS<br>4                                                                                                                                                                                                                                                                | SEATS<br>5                                   |                         |          |
| DRIVETRAIN<br>4WD                                                                                                                                                                                                                                                         | TRANSMISSION<br>AT                           |                         |          |
| FUEL<br>Petrol                                                                                                                                                                                                                                                            | STEERING<br>Right                            |                         |          |
| EXTERIOR COLOR<br>Pearl White                                                                                                                                                                                                                                             | BODY TYPE<br>Sedan                           |                         |          |
| CHASSIS NO.<br>BM9-016909                                                                                                                                                                                                                                                 | DIMENSIONS (L X W X H)<br>473 × 178 × 151 cm |                         |          |
| SALES POINTS                                                                                                                                                                                                                                                              |                                              |                         |          |
| Alloy Wheels<br>Navigation System                                                                                                                                                                                                                                         |                                              | Adaptive Cruise Control |          |
| INSPECTOR REPORT                                                                                                                                                                                                                                                          |                                              |                         |          |
| Scratches, dents, and linear scratchesSeat wear and stainsCenter console repair marksAlloy wheel scratchesUnderbody rust, corrosion, and paint marksEnd panel distortionCore support and lower support replacedRight front inner panel replacedFront side member repaired |                                              |                         |          |

[illegible]