

2011 Nissan Bluebird Sylphy Axis		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
KG11	1,997 cc		
YEAR / REG.	MILEAGE		
2011/02	40,261 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
KG11-121660	461 × 170 × 151 cm		
SALES POINTS			
Alloy Wheels		AUTECH	
Leather Seats (Leather)		Back Camera	
Navigation System			
INSPECTOR REPORT			
Mirror A-grade damage. Driver's seat: medium wrinkles, small scuffs. Door trim: small A-grade damage. Pillar trim: small A-grade damage. Steering wheel: medium scuffs. Console: small A-grade damage. Side and bumper repair marks. Exterior color fade. Exterior: thin line scratch, front bumper underside A-grade damage. Front glass: medium stone chip. Exterior: sign marks. Left quarter panel catch area AU-grade damage. Headlights: cloudy. Right side: small A-grade dent.			

[illegible]