

2011 Nissan MURANO 250XV		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
TZ51	2,488 cc		
YEAR / REG.	MILEAGE		
2011/05	28,429 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
TZ51-010774	485 × 189 × 173 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Roof Rails		Leather Seats (Leather)	
Power Seats (Front)		Side Camera	
Back Camera		Navigation System	
INSPECTOR REPORT			
Minor scratches on mirrors and door trim. Driver's seat has slight sagging, wrinkles, and scuffing. Minor stains on cargo area trim. Large crack on console. Fine line scratches on exterior front. Medium stone chip on glass. Headlights are cloudy, and the undercarriage has S-level rust/corrosion. Center speaker is dirty, and there are multiple minor dents.			

年式登録	日産	ドア数	5	ボディ形式	SUV/クロカン	特記点	
H23/	車名	グレード	250XV	燃費区分	2WD 4WD	4	
5月	ムラーノ						
車種	自動車・その他 ()	排気量	2500	型式	TZ51	国産	A・B・C
車検	- 年 月 日	燃料	ガソリン	ディーゼル		後付増設品 ()	取付・取付不可等 ()
走行	28,429 km	エンジン	ハイブリッド	AT			
外装色	パールホワイト (3P)	内装色	5人				
セー	ディーラー・車行	13,400円					
セル							
本革シート/バックシート/CD/バックカメラ/ETC横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/寒冷地仕様/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/HDDナビ/ビルセグTV/オートクルーズコントロール/シートヒーター/DVD再生/ミュージックサーバー/ミュージックプレーヤー接続/サイドカメラ							
検査入欄							
ミラー A (小) / 運転席へたり (小) / 運転席しわ (小) / 運転席すれ (小) / ドア内張り A (小) / 荷室内張りしめ (小) / コンソール製れ (大) / 外装腐蝕キズ / ガラス傷 (中) / ヘッドライトもくもり / 下廻り S 有 / センタースピカ汚劣 / 小A 小凹み							
検査入欄							
年式登録							
有 ()							
月 日 家に名義で所有する							
車検番号							
TZ51-010774							
シリアル No.							
最大積載量							