

2011 Suzuki Alto Lapin Limited		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE HE22S	DISPLACEMENT 658 cc		
YEAR / REG. 2011/09	MILEAGE 61,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE Kei			
CHASSIS NO. HE22S-211697	DIMENSIONS (L X W X H) 340 × 148 × 152 cm		
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show scuffs and wrinkles. Exterior has minor and light scratches. The overall AA rating is 3.5 points. There is XX distortion on the core support and a U-dent on the end panel.			

ORIGINAL JAPANESE AUCTION SHEET

H23/9月		メーカー スズキ		ドア枚数 5	ボディー形状 軽四	評価点 3.5																				
車名 アルトラパン		グレード リミテッド		駆動区分 2WD 4WD																						
車歴 自家用・その他 ()	排気量 660 CC	型式 HE22S	通称型式	A・B・C																						
車検 - 年 - 月 - 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)																							
走行 61,000 km	シフト インパネ	AT																								
外装色 アロマティックアクアメタリックII	カラーNo. ()	エアコン QD・AAC・WAG・()	新着品のみ O印 を記入																							
内装色 ()	乗車定員 4 人	AW	サンルーフ	革シート																						
ハンドル 左・右	輸入区分 ディーラー・並行	9,170 円	エアバック	ナビ	TV	モース																				
セールスポイント CD/E TC/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/衝突安全ボディ/シートヒーター/ベンチシート																										
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価3.5点仕入れ コアサポート歪みXX エンドパネルU			修復歴 有 () <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ/サレ</td><td>B</td><td>キズ/ヘコミ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換品</td><td>XX</td><td>交換所</td> </tr> </table>				A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換所
A	キズ	U	ヘコミ/サレ	B	キズ/ヘコミ	P	色あせ/ボケ	Q	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換品	XX	交換所																	
登録No. HE22S-211697			名義中 月 日 までに名義できる方																							
FW (トビ)			シリアル No. ()																							
内装 (ヨコ)	シロ	ヤブレ	コガ	コガ穴	オーディオ	ボク																				