

2011 Suzuki Every Wagon JP Turbo		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE ABA-DA64W	DISPLACEMENT 658 cc		
YEAR / REG. 2011/12	MILEAGE 54,944 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Kei		
CHASSIS NO. DA64W-380446	DIMENSIONS (L X W X H) 340 × 148 × 180 cm		
INSPECTOR REPORT			
Light interior stains, some rust on the undercarriage, right power mirror faulty.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23 / 12月		メーカー スズキ		ドア枚数 5		ボディ形状 軽四		評価点 4																					
		車名 エブリイワゴン		グレード JPターボ		駆動区分 4WD																							
車歴 自用用・その他()	排気量 660	型式 ABA-DA64W	通称 型式	内装 A・B・C																									
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後日取り品 (保証書・取扱説明書 等)																										
走行 54,944 マイル		インパネ	AT																										
外装色 Lブルー	カラーNo. ZLU	エアコン	装備品のみ O印 を記入																										
内装色 ()	色番号は()内に 「色番」と記入	乗車定員 4 人																											
ハンドル 左・右	輸入 区分	ディーラー	並行	リサイクル料 10,010円	預託金	エアロック	ABS	ナビ	TV																				
セールスポイント ★インタークーラーターボ★CDデッキ★ドライブレコーダー★ETC																													
検査記入欄 ルーム内薄汚れ 下廻り1部サビ 右電格不良				修復歴 有・無 ()																									
				<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ・サレ</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>						A	キズ	U	ヘコミ・サレ	B	キズ・ヘコミ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコミ・サレ	B	キズ・ヘコミ	P	色あせ・ボケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
				登録No. 月 日 までに名変できる方																									
				車体番号 DA64W-380446																									
FW (トビタ)				備A		フレ		外装																					
小		ホイール		エアロ		シリアル		No.																					
内装		ヨゴレ		シミ		ヤブレ		コガ																					
コガ穴		オーディオ穴		スレ		車輪		長さ																					
幅		高さ		最大積載量		Kg																							