

2011 Suzuki Solio 1.2 S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-MA15S	DISPLACEMENT 1,242 cc		
YEAR / REG. 2011/06	MILEAGE 43,000 km		
DOORS 5	SEATS 5		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Blue		
BODY TYPE Hatchback			
CHASSIS NO. MA15S-117743	DIMENSIONS (L X W X H) 371 × 162 × 177 cm		
SALES POINTS			
Alloy Wheels Navigation System		Power Sliding Doors (Both Sides) (Both...	
INSPECTOR REPORT			
Interior trim scratches and dirt, minor seat scuffs, minor damage present.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23/6月	メーカー スズキ	ドア枚数 5	ボディ形状 コンパクトハッチバック	駆動方式 2WD	グレード 1.2 S フルセグテレ ビ バックモニター	4WD	年 4
車種 自家用 ・ その他 ()	排気量 1200	CC	型式 DBA-MA15S	通称 ソリオ	内装 A・B・C		
車検 -	年 43	月 00	日 00	燃料 ハイブリッド	ディーゼル	後付選り品 (保証書 ・ 取扱説明書 等)	
走行 43,000	マイル	インパネ	CVT				
外装色 グレースブルーパールメタリック	カラーNo. ()	内装色 ()	エアコン	エアコン	5人	装備品のみ O印 を記入	
左・前・後 左・前・後	ディーラー	走行	リサイクル料	11,030円	預託金	エブリック	GS
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エ アバック/サイドエアバック/メモリーナビ他/フルセグT V/E TC/スマートキー/寒冷地仕様/盗難防止システム/H I D ・ キセノン ・ ディスチャージ/ウォークスルー/CD/ バックカメラ/両側電動スライドドア							
検査記入欄 室内内張傷、汚れ シートずれ小 寄造小傷有				修復歴 有・無			
AW トピ石 傷A フレ 外装 小 A・U A・曲 A・フレ エアロ シリアル No. MA15S-117743				A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修跡 S ヤビ C 腐食 X 交換部 XX 交換部			
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ				車種 長さ cm 幅 cm 高さ cm 最大積載量 kg			