

2011 Suzuki Swift XG		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ZC72S	1,242 cc		
YEAR / REG.	MILEAGE		
2011/10	69,565 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZC72S-132518	385 × 170 × 151 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Exterior has noticeable scratches and dents. Interior has some noticeable stains. No abnormalities in the frame.			

軽枠内のグレード鑑定/JAAA鑑定証の評価と下記記載の評価とは異なります														
初年度登録 H23		メーカー スズキ		ドアク数 5			ボディ形状 コンパクト/ハッチバック			評価点 4				
10月		車名 スイフト		グレード XG										
車種 自家用		年式 14	型式 ZC72S	駆動方式 1200	燃料 ガソリン	内装 B								
車検 9年	月 1	抹消	走行 69,565	マイル 69	駆動 2WD	エンジン AAC	変速機 K							
外装色 スターシルバームエタリック		カラーNo. (ZMU)		リサイクル料 11,430円		車両重量 ZC72S-132518								
()		内装色 ()		シフト フロア AT		乗車定員 5人								
後付品 (保証書・取扱説明書等)														
総額														
CD/E/C/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/AB S/助手席エアバック/メモリーナビ他/フルセグTV/DVD再生														
査定員記入欄														
※ダメージレベルに関する注意事項 細かい記号のみ 小はし 中はし 大はし 大はし														
F H23 車種 フレ 外装 A-U 内装 A-F 車検 9年 月 1 抹消 走行 69,565 マイル 69 駆動 2WD エンジン AAC 変速機 K														
クオリティグレード説明 外装: 気になるようなキズやヘコミがあります。 内装: 気になる汚れ等、部分的にあります。 修復歴: 骨格部位に異常はありません。														
車体状態の確認は、停止状態で実施する範囲で行っています。														