

2011 Toyota FJCruiser Color Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-GSJ15W	DISPLACEMENT 3,955 cc		
YEAR / REG. 2011/08	MILEAGE 88,300 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE SUV		
CHASSIS NO. GSJ15-0114264	DIMENSIONS (L X W X H) 464 × 191 × 184 cm		
SALES POINTS			
Alloy Wheels Navigation System		Cruise Control	
INSPECTOR REPORT			
Seat scuffs/wrinkles, trim, cargo area A. Rear tire cover has scratches, paint damage, and peeling. Body has light scratches, dents, and aluminum scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

型式番号 H23/	メーカー トヨタ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4
登録月 8月	車名 FJクルーザー	グレード カラーパッケージ	駆動区分 2WD	
車種 自家用・その他()	排気量 4000 cc	型式 CBA-GSJ15W	燃費 A・B・C	
年 -	月 -	日 -	燃料 ガソリン	燃料消費率 15.0 km/L
走行 88,300 km	シフト フロア 5 AT	後日課り品 ()	取扱い ()	
外装色 ツートーンブラック	カラーNo. ()	エアコン ()	新車品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ ()	高シート ()	
小 左・右 大 左・右	輸入 ディーラー 走行 13,650 km	エアロ ()	キーレス ()	
セールスポイント				
スペアキー 新車保証書 20インチオプションアルミ クルーズコントロール 純正ナビTV				
検査記入欄				
シート擦れシワ トリム 荷室A 背面タイヤカバーA P ハゲ ボディ小傷うすA U アルミスリA				
修復歴 有 ()				
A キズ U ヘコみサシ B キズヘコみ P 色あせサシ Q ガラスキズ W 腐蝕 R サビ C 腐食 X 交換部 YX 交換部 登録No. 月 日 までに名義できる方 車体番号 GSJ 15-0114264				
FW トボ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ	シリアル No.			
内装 3Dグレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ	長さ cm	幅 cm	高さ cm	最大積載量 kg