

2011 Toyota REGIUS ACE VAN Super GL		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDF-KDH206V	DISPLACEMENT 2,982 cc		
YEAR / REG. 2011/03	MILEAGE 160,400 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Minivan		
CHASSIS NO. KDH206-8033270	DIMENSIONS (L X W X H) 470 × 170 × 198 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Steering wheel wear, cargo area AU processed, some underbody rust			

ORIGINAL JAPANESE AUCTION SHEET

H23/3月		メーカー トヨタ		ドア枚数 5		ボディ形状 バン		評価点 3.5																					
車名 レジアスエースバン		グレード スーパーGL		駆動区分 2WD		4WD																							
車種 自家用・その他 ()	排気量 3000 cc	型式 LDF-KDH206V	通称 型式	内装 A・⑨・C																									
車検 年 月 日	燃料 ガソリン	シフト ハイブリッド	ステアリング	後日選り品 (保証書・取扱説明書等)																									
走行 160,400 km	インパネ	AT																											
外装色 シルバー	カラーNo.	エアコン	新車品のみ O印 を記入																										
内装色	乗車定員 5人	ABS	AW	サンルーフ	革シート																								
左・右	輸入	ディーラー	並行	10,840円	エアロック	ABS	⑨	⑩	キーレス																				
セールスポイント																													
4WD HIDライト 外品ナビ 地デジTV バックカメラ コンビハンドル					修復歴 有・⑨																								
検査記入欄					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
ハンドルスレ 荷室AU加工 下回り一部S					登録No. 名変中 月 日 までに名変できる方 車検番号 KDH206-8033270																								
FW トビ石	⑨	ワレ	外装	小	ホイール	エアロ	シリアル No.																						
内装	⑨	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	⑨	長さ cm	幅 cm																				