

2011 Toyota Vitz 5D 1.3 Juiera		OVERALL 3.5	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-NSP130	DISPLACEMENT 1,329 cc		
YEAR / REG. 2011/01	MILEAGE 95,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. NSP130-2003992	DIMENSIONS (L X W X H) 389 × 170 × 150 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Burn holes on carpet, seats, and door trim. Paint marks on pillars. Minor scratches on wheel covers and under the front bumper. Fading on front bumper and roof. Paint damage on front grille (P3) and bonnet (P2). Dent on left rear door (B2).			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H23/1月	メーカー トヨタ	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 3.5
車名 ヴィッツ	グレード 1.3 ジュエラ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1300 cc	型式 DBA-NSP130	燃費 A・B・C	内装 A・B・C
車検 10年5月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)	
走行 95,000 km	マイル フロア CVT	シフト オート		
外装色 ブラック	カラーNo. 00	エアコン	装備品のみ O印 を記入	
内装色 ()	車庫 5 人	AW	サンルーフ	革シート
バン 左・右	輸入 ディーラー	走行 10,520 km	エアバッグ	ABS
セールスポイント キーレスエントリー/メモリーナビ他/ワンセグTV/ETC/スマートキー		修復歴 有・無		
検査記入欄 カーペット焦げ穴 シート焦げ穴 ドア内張り焦げ穴 ビラーP跡 ホイールカバーA パンパー下A フロント バンパー色あせ フロントグリルP3 ボンネットP2 ルーフ色あせ 左リアドアB2あり		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・汚れ G ガラスキズ W 雨除器 S サビ C 腐食 X 交換部 XX 交換済 先付け 月 日 までに名義で売る方 車体 番号 NSP130-2003992		
FW トビ石 漏A フレ 外装 小 ホイル エアロ シリアル No.	内装 ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺	車検 ① ② ③ ④ ⑤ ⑥ ⑦ ⑧ ⑨ ⑩ ⑪ ⑫ ⑬ ⑭ ⑮ ⑯ ⑰ ⑱ ⑲ ⑳ ㉑ ㉒ ㉓ ㉔ ㉕ ㉖ ㉗ ㉘ ㉙ ㉚ ㉛ ㉜ ㉝ ㉞ ㉟ ㊱ ㊲ ㊳ ㊴ ㊵ ㊶ ㊷ ㊸ ㊹ ㊺		