


2012 Daihatsu Mira eS G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA300S	DISPLACEMENT 658 cc		
YEAR / REG. 2012/04	MILEAGE 33,021 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pink	BODY TYPE Kei		
CHASSIS NO. LA300S-1090950	DIMENSIONS (L X W X H) 340 × 148 × 150 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Right side repair history, right center pillar distortion, AC malfunction, dead battery			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H24/4月		メーカー ダイハツ		ドア枚数 5	ボディ構造 軽四	評価点 R																				
車名 ミライース		グレード G		駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-LA300S	通称 型式	内装 A・⑨・C																						
車検 9年4月	抹消 燃料 ハイブリッド	エンジン ディーゼル	後日送り品 (保証書・取扱説明書等)																							
走行 33,021 km	シフト AT																									
外装色 ピンク	カラーNo. T28	エアコン AG・QG・WAG・()	新着品のみ O印 を記入																							
内装色 ()	乗車定員 4人	⑨	⑨	⑨	サンルーフ	革シート																				
ハンドル 左・(右)	輸入 区分	ディーラー 並行	7,320円	エアバック	ABS	ナビ																				
セールスポイント スマートキー、プッシュスタート、純正アルミホイール、ウインカードアミラー																										
検査記入欄 右面修復歴 右センターピラー・ヒズミ、AC不良、BT上がり		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ・ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ・ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ・ボケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
登録No. 月 日 までに名義できる方		名義中																								
車検 番号 LA300S-1090950																										
FW トピ石	備A	ワレ	外装 ⑨・⑨	小 ⑨・⑨	乗入れ A・ワレ	エアロ No.																				
内装 ⑨	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ																				
長さ cm	幅 cm	高さ cm	最大積重量 kg																							