

2012 Honda N-BOX 660 G Turbo Package 4WD

OVERALL		3
EXTERIOR		INTERIOR
-		-

MODEL CODE DBA-JF2	DISPLACEMENT 658 cc
YEAR / REG. 2012/12	MILEAGE 99,000 km
DOORS 5	SEATS 4
DRIVETRAIN 4WD	TRANSMISSION AT
FUEL Petrol	STEERING Right
EXTERIOR COLOR Gray	BODY TYPE Hatchback
CHASSIS NO. JF2-2004388	DIMENSIONS (L X W X H) 340 × 148 × 180 cm

SALES POINTS

Alloy Wheels	Power Sliding Doors (Both Sides) (Both...
Cruise Control	

INSPECTOR REPORT

Trunk floor has minor distortion. Exterior has touch-up paint marks. Undercarriage has significant rust. Door mirror has minor scratches. Headlights are cloudy. Rear left power window is faulty. Undercarriage rust prevention has a hole and requires inspection. Interior has scratches. Front bumper has severe scratches. Engine room has rust. Interior has light stains. Steering wheel has scuffs. Seats have medium stains and scuffs.

ORIGINAL JAPANESE AUCTION SHEET

出品票		車両識別番号		シリアル番号		評価点	
型式	車名	ドア数	グレード	駆動	評価点		
H24 12月	N-BOX	5	660 G ターボパッケージ	4WD	3		
型式	DBA-JF2	排気量	660 cc	燃料	ガソリン	色	白
車種	軽自動車	車体	自家用	シフト	DAT	AC	純正装備品
走行距離	99000	マイル	0	0	0	0	純正ナビ
外装色	グレー	色別無	カラー無	内装色	白		純正ナビ
車台番号	JF2	2004388					純正ナビ
登録年	4	登録月	12	登録日	9,790	内装色	白
輸入車のみ	モーター	輸入区分	ディーラー	車行	ハンドル	右	純正ナビ
セールスポイント							
注意事項・不具合箇所							
検査済記入欄・検査済「有」の項目は検査箇所・交換箇所を記入							
トングカブリ 外装劣化							
下廻りS大 ドアミラー							
ヘッドライト 腐食 (後左)							
下廻り防錆 穴有下見							
室内腐有 腐食 (後左)							
エンジンルーム有							
室内腐汚							
ヘッドライト							
ケツミ中 ケツミ有							
トングカブリ 外装劣化							
下廻りS大 ドアミラー							
ヘッドライト 腐食 (後左)							
下廻り防錆 穴有下見							
室内腐有 腐食 (後左)							
エンジンルーム有							
室内腐汚							
ヘッドライト							
ケツミ中 ケツミ有							