

2012 MAZDA CX-5 XD		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LDA-KE2FW	DISPLACEMENT 2,188 cc		
YEAR / REG. 2012/04	MILEAGE 82,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Diesel	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE SUV		
CHASSIS NO. KE2FW-102093	DIMENSIONS (L X W X H) 454 × 184 × 171 cm		
SALES POINTS			
Alloy Wheels Back Camera		Side Camera Cruise Control	
INSPECTOR REPORT			
Light interior stains and scuffs, left front fender stay bent, rear spoiler paint peeling, exterior faded.			

初年度登録		メーカー		ドット数		ボディ形状		評価点	
H24 / 4月		マツダ C X-5		グレード XD		SUV/クロカン		車種区分 2WD 4WD	
車種 良型用・その他()		積重量 2200 CC		型式 LDA-KE2FW		運転形式		内装 A・B・C	
車検 - - 年 / 月 ()		燃料 ガソリン		変速機 オートマチック		後日返却品 (保証書・取扱説明書等)			
走行 口内にマークを記入(※交換・劣化品は○印で示す) [] 万 [] 千 [] 百 [] 十 [] 円 [] 角 [] 分 [] 秒		シフト フロア AT							
外装色 レッド ()		カラーNo. AG・WG・WAG・()		装備品のみに○印を記入					
()		内装色 標準定員 5人		F6 F7 AM サンルーフ 革シート					
ハサビ		左・右		入力		ディーラー		走行	
価格		11,650円		税別		EPA A B C D E F G H I J K L M N O P Q R S T U V W X Y Z			
セールスポイント									
スマートキー CDオーディオ ETC アイドリングストップ オートライト フォグ ウインカーミラー 純正AW									
検査記入欄									
内装薄汚れ・スレ 左Fフェンダーステー歪み Rスパillage 外装色褪せ									
修理履歴 有 ()									
A	型式	U	ヘコキヤレ	B	ガラス割れ	P	熱傷・火傷	G	ガラス割れ
W	修理箇所	S	錆び	C	腐食	X	交換済	XX	交換済
登録No.	月 日 までは名義である								
車体番号	KE2FW-102093								
FW	トピ石	備A	フレ	外装	小	ホイール	エアロ	シリアル	
内装	()	シミ	ヤブレ	コゲ	コガタ	オーデイオス	()	車庫	最大積載量