

2012 Nissan Serena 20G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-C26	DISPLACEMENT 1,997 cc		
YEAR / REG. 2012/03	MILEAGE 100,985 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Minivan		
CHASSIS NO. C26-037063	DIMENSIONS (L X W X H) 469 × 170 × 187 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Sliding Doors (Both Sides) (Both...		Cruise Control	
Front Camera		Back Camera	
Rear Seat Entertainment (Rear Seat Ent...		Navigation System	
INSPECTOR REPORT			
Power window stone chip. Interior: dirt, stains, tear. Exterior: cracks, small scratches, small holes. Wheels: bent, cracked. Aero parts: cracks. Audio hole, scuffs.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H24 3月	メーカー 日産	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 R
車種 自家用・その他 ()	排気量 1990 cc	型式 DBA-C26	登録区分 4WD	内装 A・B・C
車検 9年1月	燃料 ガソリン	ディーゼル	後付部品 ()	
走行 100,985 km	変速機 AT			
外装色 パール	カラーNo. QAB	エアコン AG・WG・WAG ()	新車のみのO印を記入	
内装色 その他	乗車定員 8人	PS	サンルーフ	キーレス
左・右 左	ディーラー	12,260円	ABS	ナビ
セールスポイント				
クルーズコントロール オートライト ALPINE フリップダウンモニター 後席サンシェード、デスク スカッフプレート?				
検査記入欄				
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				
名義中				
月 日				
C26-037063				
kg				