

2012 Nissan Serena 20X		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-C26	DISPLACEMENT 1,997 cc		
YEAR / REG. 2012	MILEAGE 72,177 km		
DOORS 5	SEATS 8		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. C26-040935	DIMENSIONS (L X W X H) 468 × 169 × 186 cm		
SALES POINTS			
Cruise Control		Navigation System	
INSPECTOR REPORT			
Windshield stone chip. Front bumper has scratches and touch-ups. Various scratches and touch-ups on front fender, hood, doors, quarter panels, rear bumper, side steps, roof, and rear gate. Door mirrors and wheels have scratches. Interior has dirt, stains, and tears. Audio hole. No spare tire.			

初年度登録 H24 / 一月	メーカー 日産	ドア数 5	ボディ形状 ミニバン/ワンボックス	評価点 R																				
車種 自家用・その他 ()	排気量 1990	型式 DBA-C26	運転形式 AT	内装 A・⑤・C																				
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル ハイブリッド ()	後日送り品 (保証書・取扱説明書 等)																					
走行 [] 万 千 1 7 7 マイル	シフト CVT																							
外装色 ブラック	カラーNo. ④	装備品の目 O印 を記入																						
()	内装色 車庫定員 人	PS	PW	AW																				
ハンドル 左・交	輸入 区分	ディーラー	走行 マイル制	0 円 / 100 円																				
セールスポイント																								
検査記入欄		修復歴 ①, 無 <table border="1"> <tr> <td>A</td> <td>キズ</td> <td>U</td> <td>ヘコみ/サシ</td> <td>B</td> <td>キズ/ヘコみ</td> <td>P</td> <td>色あせ/変色</td> <td>G</td> <td>ガラス/キズ</td> </tr> <tr> <td>W</td> <td>経路跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </table> 登録地 月 日 までに名義できる 車体番号 C26-040935 シリアル No. 車庫 長さ 468 cm 幅 169 cm 高さ 186 cm 最大積載量			A	キズ	U	ヘコみ/サシ	B	キズ/ヘコみ	P	色あせ/変色	G	ガラス/キズ	W	経路跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サシ	B	キズ/ヘコみ	P	色あせ/変色	G	ガラス/キズ															
W	経路跡	S	サビ	C	腐食	X	交換済	XX	交換済															