

2012 Suzuki Alto Lapin X 4WD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-HE22S	658 cc		
YEAR / REG.	MILEAGE		
2012/06	105,187 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Other		
CHASSIS NO.	DIMENSIONS (L X W X H)		
HE22S-244659	339 × 147 × 152 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Front windshield stone chips. Interior has scratches, dirt, and scuffs. Steering wheel scuffs. Left and right center pillars have paint issues. Rear bumper color is faded. Underbody paint shows rust and corrosion. Upper support has traces of repair/damage.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	16173	車両識別番号	0604	シリアル番号		評価点	
年	月	日	車名	グレード	駆動	2WD	3.5		
H 24	6		7&トラン	X 4WD	5				
型式	DBA-HE22S	前駆重	660 cc	燃費	10.0 km/L	経年			
車種	R 09	年	6	車種	自家用	シフト	CVT	冷却	AC
走行距離	105,187 km	マイル	67,311	色	白	純正装備品	○をつける	純正TV	
外装色	白	色	白	カラーNo.		純正ナビ	○をつける	SR	
車台No.	HE22S-244659	名義		月	日	純正AW	○をつける		
登録No.	函館 580 K 3462	リサイクル	9,070円	未納税		TV録画 (社外品含む)	○をつける		
定員	4人	積載量	339 kg	長さ	147 cm	フルセグ	ワンセグ	アナログ	
輸入車のみ	モデリ	年	2012	輸入区分	ディーラー	ナビ録画 (社外品含む)	○をつける		
セールスポイント						DVD再生可	CD	SD	
						後付発注品	○をつける		
						新車保証書		車検取得	

注意事項・不具合箇所

AC不良

検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入

FR 飛石

内装 キズ、汚れ、スレ

ハンドルスレ 左右センターピラーペイント

リヤバンパー 色アセ

下廻りペイントサビフシヨク

アッパーサポートB跡

ドアミラー	キズ	ヒビ	ワレ
工具	無	シャッキ	無