


2012 Toyota HIACE VAN DX		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBF-TRH200V		DISPLACEMENT 1,998 cc	
YEAR / REG. 2012/05		MILEAGE 54,579 km	
DOORS 4		SEATS 3	
DRIVETRAIN 2WD (FR)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR White		BODY TYPE Minivan	
CHASSIS NO. TRH200-0161356		DIMENSIONS (L X W X H) 470 × 170 × 198 cm	
INSPECTOR REPORT			
Rear panel has minor undulation/repair. Cargo area has minor damage. Traces of signboard. Partition bar is missing.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H24/5月		メーカー トヨタ		ドア枚数 4	ボディ形状 バン	評価点 4																				
車名 ハイエースバン		グレード DX		駆動区分 2WD 4WD																						
車歴 自用・その他 ()	排気量 1990	型式 CC	CBF-TRH200V		通称 型式	内装 A・B・C																				
車検 - - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書等)																							
走行 54,579 km		インパネ	AT																							
外装色 ホワイト	カラーNo. (058)	エアコン	新備品のみ O印 を記入																							
()	内装色	乗車定員 3人	PS	PA	AW	サンルーフ																				
ハンド 左・右	輸入 区分	ディーラー	並行	リサイクル料	10,430円	預託金																				
セールスポイント キーレス		3																								
検査記入欄 RパネルWU 荷室AU カンパン跡 仕切り棒欠																										
		修復歴 有 (馬)																								
		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘコミ・凹み</td><td>B</td><td>キズ・ヘコミ</td><td>P</td><td>色あせ・剥落</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換所</td> </tr> </table>					A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所
A	キズ	U	ヘコミ・凹み	B	キズ・ヘコミ	P	色あせ・剥落	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換所																	
		登録No. 月 日 まで(に)名義できる方																								
		車体 番号 TRH200-0161356																								
		シリアル No.																								
PW	トド石	丸	フレ	外装	小 A・G	ホイール A・曲	エアロ A・フレ																			
内装	ヨコ	シミ	ヤブレ	コゲ	コゲ穴	オーディ穴	スレ																			
長さ	469 cm	幅	169 cm	高さ	198 cm	最大積載量 1250 Kg																				