

2012 SUBARU XV 2.0i-L EyeSight		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GP7	DISPLACEMENT 1,995 cc		
YEAR / REG. 2012/12	MILEAGE 62,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. GP7-027660	DIMENSIONS (L X W X H) 445 × 178 × 160 cm		
SALES POINTS			
Alloy Wheels Navigation System		Adaptive Cruise Control	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior small scratches and light scratches, purchased with AA 4-point rating, D mirror malfunction, minor rust underneath.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H24 12月	メーカー スバル	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 4
車名 XV	グレード 2.0i-L	駆動方式 2WD	燃費区分 4WD	
車種 自家用・その他	排気量 2000 cc	型式 GP7	選別形式	内装 A・B・C
車検 - 年 月	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)	
走行 62,000 km	シフト フロア	AT		
外装色 デザートカーキ	カラーNo. QD	エアコン	新着品のみ O印 を記入	
内装色 QD	乗車定員 5人	ドアロック	サンルーフ	高シート
小回り 左・右	輸入 ディーラー	走行 12,030 km	エアロック	エア
セールポイント パワーシート/CD/ETC/横滑り防止装置 (ESC)/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/4WD/アイドリングストップ/DVD再生				
検査記入欄 内装キズ、汚れ シートスレ、シワ 外装キズ、擦キズ AA評価4点仕入れ Dミラー作動不良 下回りさび小				
修理歴 有・無				
A キズ U ヘコみサレ B キズヘコみ P 色あせ・汚れ Q ガラスズレ W 腐蝕跡 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 までに名義できる方				
車体番号 GP7-027660				
FW	エンジン	変速機	エアロ	シリアル
内装	シロ	ヤブレ	コガ	コガ