

2013 Audi Audi Q3 2.0 TFSI quattro 211 PS		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ABA-8UCPSF	DISPLACEMENT 1,984 cc		
YEAR / REG. 2013/05	MILEAGE 49,500 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE SUV		
CHASSIS NO. WAUZZZ8U3DR094981	DIMENSIONS (L X W X H) 439 × 183 × 162 cm		
SALES POINTS			
Alloy Wheels Power Seats (Front) Navigation System		Roof Rails Back Camera	
INSPECTOR REPORT			
Small scratches and small dents			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/5月	メーカー アウディ	ドア枚数 5	ボディ形状 SUV/クワカン	評価点 4.5
車名 Q3	グレード 2.0 TFSI クワトロ 211 PS	駆動区分 2WD	4WD	
車歴 自家用・その他 ()	2000 cc	型式 ABA-8UCPSF	通称 形式	内装 A・B・C
車検 8年10月 / 抹消	燃料 ガソリン	ディーゼルのハイブリッド ()	後日取り込み ()	取付 ()
走行 49,500 km	フロア	AT		
外装色 パール	カラーNo. ()	AG・BG・WAG・ ()	装備品のみ O印 を記入	
内装色 ()	車庫定員 人	()	サンルーフ	革シート
左・前・後 左・前・後	走行 18,450 km	タイヤ 18,450 km	エアロ	その他
セールスポイント				
★4WD★パワーシート★純正ナビ★スマートキー★Pスタート★フルセグTV★バックモニター★Bluetooth★CD & DVD再生★純正18インチAW★コーナーセンサー★HID★オートライト★ルーフレール★ETC★スベアキー有★				
検査記入欄				
小傷・小凹み				
修復歴 有 ()				
A キズ U ヘッドライト B キズ・ヘッド P 熱劣化・サビ Q ガラスキズ W 腐蝕 S サビ C 腐食 X 交換済 YX 交換済				
名義中				
月 日 までに名義できる方				
車体番号 WAUZZZ8U3DR094981				
シリアル No.				
kg				