

2013 BMW BMW X1 sDrive 20i Sport		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-VL20	DISPLACEMENT 1,997 cc		
YEAR / REG. 2013/09	MILEAGE 66,287 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE SUV		
CHASSIS NO. WBAVL92020VU21118	DIMENSIONS (L X W X H) 449 × 180 × 155 cm		
SALES POINTS			
Alloy Wheels Leather Seats Back Camera		Sunroof Power Seats (Front) Navigation System	
INSPECTOR REPORT			
PW: Stone chips. Interior: Stains, wrinkles, wear around audio hole.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/9月	メーカー BMW	ドア枚数 5	ボディ形状 SUV/クワカン	評価点 4.5
車名 X 1	グレード sDrive 20i スポーツ	駆動方式 4WD	4WD	
車歴 自家用・その他 ()	年式 1990	型式 DBA-VL20	通称 形式	内装 A・⑤・C
車検 8年10月 / 抹消	燃料 ガソリン	ディーゼル	後日選り込み (保証書・取扱説明書 等)	
走行 66,287 km	シフト AT			
外装色 ネイビー	カラーNo. 0	AG・⑤・WAG・ ()	装備品のみ O印 を記入	
()	内装色 ブラック	乗車定員 5人	PS	サンルーフ
左・前 20,470円	右・後 20,470円	エアロ	ABS	ナビ
セールスポイント				
0				
検査記入欄				
A ボディ U ヘッドライト B キズ・ヘコみ P 熱帯地域 X 交換部 XX 交換済				
W 補修部 S サビ C 腐食				
車検No. 月 日 まで有効				
車体番号 WBAVL92020VU21118				
内装 ⑤	ボディ ⑤	ホイール ⑤	エアロ ⑤	シリアル No.
内装 ⑤	ボディ ⑤	ホイール ⑤	エアロ ⑤	シリアル No.