

| 2013 BMW BMW Z4 sDrive20i Highline                                                                                                                                                                          |                                              | OVERALL                                      |          |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----------------------------------------------|----------|
|                                                                                                                                                                                                             |                                              | 4                                            |          |
|                                                                                                                                                                                                             |                                              | EXTERIOR                                     | INTERIOR |
|                                                                                                                                                                                                             |                                              | -                                            | -        |
| MODEL CODE<br>LL20                                                                                                                                                                                          | DISPLACEMENT<br>1,997 cc                     |                                              |          |
| YEAR / REG.<br>2013/05                                                                                                                                                                                      | MILEAGE<br>73,489 km                         |                                              |          |
| DOORS<br>2                                                                                                                                                                                                  | SEATS<br>2                                   |                                              |          |
| DRIVETRAIN<br>2WD (FR)                                                                                                                                                                                      | TRANSMISSION<br>AT                           |                                              |          |
| FUEL<br>Petrol                                                                                                                                                                                              | STEERING<br>Right                            |                                              |          |
| EXTERIOR COLOR<br>White                                                                                                                                                                                     | BODY TYPE<br>Convertible                     |                                              |          |
| CHASSIS NO.<br>WBALL320X0J081566                                                                                                                                                                            | DIMENSIONS (L X W X H)<br>425 × 179 × 129 cm |                                              |          |
| SALES POINTS                                                                                                                                                                                                |                                              |                                              |          |
| Alloy Wheels<br>Power Seats (Front)                                                                                                                                                                         |                                              | Leather Seats (Leather)<br>Navigation System |          |
| INSPECTOR REPORT                                                                                                                                                                                            |                                              |                                              |          |
| Exterior: Noticeable scratches and dents have been repaired, but minor scratches and dents remain.<br>Interior: Some noticeable dirt and stains are present. Repair History: No abnormalities in the frame. |                                              |                                              |          |

[illegible]