

2013 BMW_Mini BMW Mini 3HB Cooper		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-SU16	DISPLACEMENT 1,598 cc		
YEAR / REG. 2013/05	MILEAGE 78,100 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. WMWSU320X0T628767	DIMENSIONS (L X W X H) 374 × 169 × 143 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Light interior dirt, carpet burns, steering wheel wear, seat wrinkles, small scratches on door mirrors, wheel scratches.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H25 / 5月	メーカー MINI 車名 MINI クーバー	ドア枚数 3	ボディ形状 コンパクト/ハッチバック	評価点 4
車種 自家用・その他 ()	排気量 1600 CC	型式 CBA-SU16	通称 型式	内装 A・B
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	検出通り品 (保証書・取扱説明書 等)	
走行 78,100 km	シフト フロア 6 AT	エンジン AG・AG・WAG・ ()	装備品のみ O印 を記入	
外装色 シルバー・ゴールド	カラーNo. ()	乗車定員 4 人	PS	PW
内装色 ()	ドア 左・右	ナビゲーション 15,990円・販売額	エアバック	ABS
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/メモリーナビ他/フルセグTV/ETC/H I D・キセノン・ディスプレイ/横滑り防止装置 (E S C) /ミュージックプレイヤー接続可/CD/M Tモード付き				
検査記入欄 ルーム内うす汚れ カーベットコゲ ハンドルスレシートしわ ドアミラー小キズ ホイールキズ				
車検No. 月 日 までにも名実できる方				
車体番号 WMWSU320X0T628767				
FW トボ石	フレ	外装	小	ホイール
内装	シス	ヤブレ	コ	コグス
エアロ	シリアル No.	長さ	幅	高さ
重量	cm	cm	cm	kg