

2013 BMW X3 xDrive 28i M Sport Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE WX20	DISPLACEMENT 1,997 cc		
YEAR / REG. 2013/02	MILEAGE 78,800 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE SUV		
CHASSIS NO. WBAWX92050LL18912	DIMENSIONS (L X W X H) 466 × 190 × 168 cm		
SALES POINTS			
Alloy Wheels Power Tailgate Cruise Control Side Camera Navigation System		Roof Rails Power Seats (Front) Front Camera Back Camera	
INSPECTOR REPORT			
Exterior: Major scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some areas have noticeable dirt. Repair history: No abnormalities in the frame.			

新車登録		メーカー		B M W		ドア数		5		ボディ形状		SUVクロカン		評価点	
H25/		2月		X 3		xDrive ポツパッケージ		28i		Mス		4.5			
車種		車名		型式		右		型式		2000		変速機		ガソリン	
車種		ディーラー		型式		右		型式		2000		変速機		ガソリン	
年		月		日		7		8		10		マル		4WD	
外見色		ホワイト		カラーNo.		リサイクル料		23,670円		期間税		WBAWX9205OLL18912		車検	
()		()		シフト		フロア		AT		乗車定員		5人		車検	
新車引込み		(保証書・取扱説明書等)		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検		車検		車検		車検		車検		車検		車検		車検	
車検															