

2013 BRZ 2.0 S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-ZC6	DISPLACEMENT 1,998 cc		
YEAR / REG. 2013/06	MILEAGE 68,000 km		
DOORS 2	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Coupe		
CHASSIS NO. ZC6-010096	DIMENSIONS (L X W X H) 424 × 178 × 130 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Underbody rust, minor exterior scratches and dents, seat scuffs, steering wheel scuffs, interior dirt. Front glass has scratches, stone chips, cracks, repair marks, and requires replacement. Interior has scratches, dirt, burns, holes, scuffs, tears, and rips.			

ORIGINAL JAPANESE AUCTION SHEET

初度登録年月 平成25年 6月	車名・グレード BRZ S	2WD 4WD	評価点 (4)		
ディーラー・並行 モデル年式 ハンドル 左・右	型式 DBA-ZC6	排気量 2000 CC	ドア 2		
		定員 4人	形状 CP		
		積載 kg	外装 C		
			内装 B		
車種 自家用	シフト FAT	セールスポイント (正常に機能するものに限りです)			
車検 年 月 (日)	冷房 AAC	キーレススマートキー・H1Dヘッドライト			
走行 6万7千360 km	燃料 ガソリン				
色 シルバー	色替 色コード D6S	装備品 (純正品に限り○をつけてください)			
R券 10,180 円		(PS) (PW) (BS) (AB) (AW) SR ナビ TV カフ			
注意事項申告欄		新車保証書 有・無			
下回り サビ					
外装 小A・小U					
シート すれ					
ハンドル すれ					
室内 汚れ					
フロントガラス キズ・破石・ヒビ割・リペア跡・X要	内装 キズ・破れ・コゲ・穴・スレ・キレ・破れ	A-キズ E-エクボ U-凹み W-補修跡 S-サビ C-腐食 XX-交換済			
車台番号 010096		型式指定番号 参考			
登録番号		車検取得月 参考			