


2013 SUBARU BRZ S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-ZC6	DISPLACEMENT 1,998 cc		
YEAR / REG. 2013/02	MILEAGE 95,000 km		
DOORS 2	SEATS 4		
DRIVETRAIN 2WD (FR)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Coupe		
CHASSIS NO. ZC6-008659	DIMENSIONS (L X W X H) 424 × 178 × 130 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Full repaint (code 2170), minor scratch on mirror, medium wear on steering wheel, wear on shift knob, lower support dented, wear on driver's seat (code 2073), minor scratch on console (code 2073), medium scratches/chips on front windshield (codes 1221, 12143)			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/2月	メーカー スバル 車名 BRZ	ドア枚数 2	ボディ形状 クーペ	評価点 4
車種 自家用・その他 ()	年式 1998	型式 DBA-ZC6	変速方式 内装	A・B・C
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日添付品 (保証書・取扱説明書 等)	
走行 95,000 km	マイル フロア 6 MT			
外装色 WRブルーマイカ	カラーNo. AAG・WAG・ ()	装備品のみのO印を記入		
内装色 ()	乗車定員 4人	PS	PW	サンルーフ
ベンチ 左・右	ディーラー 走行	15,000円	エレクトロニック	ナビ
セールスポイント キーレスエントリー/ABS/運転席エアバック/サイドエアバック/スマートキー/盗難防止システム/HID・キセノン・ディスチャージ横滑り防止装置(ESC)/フルフラット				
検査記入欄 問題点2170オールペイント シートA ハンドルすれ・中 シフトノブすれ ロアサポート裏上げ 運転席すれ・<車検2073> コンソールA・<車検2073> イガラス裏面2214・<車検2143>		修復歴 有・B		
A キズ		U へこみ	B キズ・へこみ	P 色あせ・汚れ
W 経年劣化		S サビ	C 腐食	X 交換部
名 家		名 家		
月		日		
車体番号 ZC6-008659				
FW トビ石		漏A シモ	フレ ヤブレ	外装 小 A・U
内装 ミゴレ		シモ	ヤブレ	コガ コガ穴
		スレ	スレ	スレ
車検 cm		cm	cm	最大重量 Kg