

2013 Daihatsu Move Custom Custom RS		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-LA100S	658 cc		
YEAR / REG.	MILEAGE		
2013/03	79,000 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Pearl White	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
LA100S-0215294	340 × 148 × 162 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
Navigation System			
INSPECTOR REPORT			
Small scratches and dents, scratches/scuffs inside the cabin.			

初年度登録		メーカー ダイハツ		ドア数 5		ボディ形状 軽四		駆動部																																									
H25 / 3月		車名 ムーヴ		グレード カスタム RS		燃費区分 6WD 4WD		4																																									
車種 良用途・その他（ ）		排気量 660 CC		型式 DBA-LA100S		運転形式		内装 A・B・C																																									
車検 10年3月 抹消		燃料 モーター ハイブリッド		ディーゼル		後日選り貼（ B ）※取扱い明書等（ ）																																											
走行 口内にマークを記入（※交換 ※盗竊 ※失窃） シフト マイル CVT																																																	
外装色 パール カラーNo. (W24)		エンジン AG・QG・WAG・()		装備品のみ O印 を記入																																													
()		色番号は1桁以内に入力（右側）と記入		標準定員 4人		Fg Fy AM サンルーフ 革シート																																											
ハンドル 左・ R 変速 部分		ディスターンター・並行		リサイクル料 8,490円・預託金		エアバック		ABS ESP TP モーリス																																									
セールスポイント																																																	
ターボ付 B バッテリー AUTOライト LEDヘッド ランプ MOMOステアリング アイドリングストップ Bluetooth対応 DVD視聴可能 P ユニキャスト ETC																																																	
検査記入欄																																																	
小キズ小凹 ルーム内キズスレ																																																	
修復歴 有・N <table border="1"> <thead> <tr> <th>A</th> <th>劣化</th> <th>U</th> <th>へこみ割れ</th> <th>B</th> <th>劣化へこみ</th> <th>P</th> <th>熱影響部</th> <th>G</th> <th>ガラスキズ</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>修理済</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </tbody> </table> 登録地 No. _____ 月 _____ 日 までに名義である 車体番号 LA100S-0215294 <table border="1"> <thead> <tr> <th>FW</th> <th>トピ石</th> <th>傷A</th> <th>フレ</th> <th>外装</th> <th>小キズ</th> <th>ホイール</th> <th>エアロ</th> <th>シリアル No.</th> <th>総重量</th> </tr> </thead> <tbody> <tr> <td>内装</td> <td>ヨゴレ</td> <td>シミ</td> <td>ヤブレ</td> <td>コガ</td> <td>コガ穴</td> <td>オーデイオ</td> <td>スレ</td> <td>車庫</td> <td>最大積載量</td> </tr> </tbody> </table>										A	劣化	U	へこみ割れ	B	劣化へこみ	P	熱影響部	G	ガラスキズ	W	修理済	S	サビ	C	腐食	X	交換済	XX	交換済	FW	トピ石	傷A	フレ	外装	小キズ	ホイール	エアロ	シリアル No.	総重量	内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーデイオ	スレ	車庫	最大積載量
A	劣化	U	へこみ割れ	B	劣化へこみ	P	熱影響部	G	ガラスキズ																																								
W	修理済	S	サビ	C	腐食	X	交換済	XX	交換済																																								
FW	トピ石	傷A	フレ	外装	小キズ	ホイール	エアロ	シリアル No.	総重量																																								
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーデイオ	スレ	車庫	最大積載量																																								