

2013 Daihatsu Tanto 660 X SA		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-LA600S	DISPLACEMENT 658 cc		
YEAR / REG. 2013/12	MILEAGE 120,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. LA600S-0021715	DIMENSIONS (L X W X H) 340 × 148 × 175 cm		
SALES POINTS			
Power Sliding Doors (Both Sides) (Drive... Back Camera		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Seat stains and sagging, Wheel A, Steering wheel wear, Right floor distortion, End panel bent			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/12月	メーカー ダイハツ	ドア枚数 5	ボディ形状 コンパクトハッチバック	グレード 660 X SA	駆動区分 2WD	登録区分 4WD	車種 R
車名 タント	型式 DBA-LA600S	排気量 660	CC 658	燃料 ガソリン	ディーゼル	後付け部品 (保証書・取扱説明書等)	内装 A・B・C
走行 120,000	インパネ CVT	エアコン	エアコン	ナビ付	ナビ付	後付け部品 (保証書・取扱説明書等)	内装 A・B・C
外装色 パールホワイトIII	カラーNo. ()	内装色 ()	乗車定員 4人	AW	サンルーフ	革シート	後付け部品 (保証書・取扱説明書等)
左・前 左・前	ディーラー ディーラー	走行 走行	リサイクル料 9,550円	エコパック	エコパック	エコパック	エコパック
セールスポイント				修復歴			
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/メモリーナビ他/衝突被害軽減ブレーキ/ETC/アイドリングストップ/スマートキー/盗難防止システム/横滑り防止装置 (ESC) /ベンチシート/バックカメラ/両側スライド片側電動ドア				修復歴			
検査記入欄				修復歴			
シートシミ、ヘタリ				修復歴			
ホイールA				修復歴			
ハンドルスレ				修復歴			
Rフロア歪み				修復歴			
エンドパネル曲がり				修復歴			
FW	トビ石	傷A	ワレ	小	ホイール	エアロ	シリアル
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ	スレ
車種	cm	cm	cm	cm	cm	cm	cm