

2013 Honda ACCORD Hybrid 2.0 EX		OVERALL 4	
		EXTERIOR -	INTERIOR -
MODEL CODE DAA-CR6	DISPLACEMENT 1,993 cc		
YEAR / REG. 2013/09	MILEAGE 65,439 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Sedan		
CHASSIS NO. CR6-1004193	DIMENSIONS (L X W X H) 491 × 185 × 146 cm		
SALES POINTS			
Alloy Wheels Pre-Collision Braking Back Camera		Power Seats (Front) Adaptive Cruise Control Navigation System	
INSPECTOR REPORT			
Door mirror scratches, wheel scratches, minor exterior scratches (A) and dents (U), front fender stay damaged. Interior has dirt and trim scuffs. Front windshield has scratches, stone chips, cracks, repair marks, and needs replacement. Interior also has scratches, dirt, burns, holes, scuffs, tears, and rips.			

[illegible]