

2013 Honda FIT 13GF Package		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE GK3	DISPLACEMENT 1,317 cc		
YEAR / REG. 2013/10	MILEAGE 55,872 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. GK3-1010668	DIMENSIONS (L X W X H) 396 × 170 × 153 cm		
SALES POINTS			
Alloy Wheels Navigation System		Back Camera	
INSPECTOR REPORT			
Exterior: Notable scratches and dents have been repaired, but minor scratches and dents remain. Interior: Some noticeable stains and dirt are present in parts. Repair History: No structural damage.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H25 10月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 3.5
車名 フィット	グレード 13G・Fパッケージ			
車種 自家用	型式 右	GK3	排気量 1300	燃料 ガソリン
走行 55,872 km	カラーNo. アパステルシルバーメタリック	リサイクル料 9,880円	車台番号 GK3-1010668	重量 1300 kg
シフト フロア	AT	5人		

後口送り状
(印) 取送明書 等)

セールスポイント

CD/フルフラット/ETC/傾斜防止装置 (ESC) 運転席エアバック/乗員防止システム/スマートキー/キーレスエントリ/A B S /助手席エアバック/メモリーナビ/衝突安全ボディ/アイドリングストップ、バックカメラ。

査定員記入欄

Fサポート X X

ボグマージレベルに関する注意事項

車検は配等のみ

外装: 気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。

内装: 気になる汚れ等が、部分的にあります。

修復歴: 骨格部位に異常はありません。

車両状態の図解

車両状態の図解

車両状態の図解