

2013 Honda N-BOX G L Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF1	DISPLACEMENT 658 cc		
YEAR / REG. 2013/03	MILEAGE 59,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. JF1-1210657	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Drive...	
INSPECTOR REPORT			
Interior scuffs, steering wheel scuffs			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/3月		メーカー ホンダ		ドア枚数 5	ボディ構造 軽四	評価点 4.5																				
車名 N-BOX		グレード GLパッケージ		駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-JF1	通称 型式	内装 A・⑨・C																						
車検 10年3月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)																							
走行 59,000 km	シフト インパネ	AT																								
外装色 アプラスターシルバームタリック	カラーNo. ()	エアコン ()	新着品のみ O印 を記入																							
内装色 ()	乗車定員 4人	PS	サンルーフ	車シート																						
ハンド 左・右	輸入 区分	ディーラー	並行	9,790円	ナビ	TV																				
セールスポイント																										
キーレスエントリー/A B S /運転席エアバック/アイドリ ングストップ/スマートキー/横滑り防止装置 (E S C) / CD/片側電動スライド			修復歴 有・⑨																							
検査記入欄			<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ・へこみ</td><td>P</td><td>色あせ/サケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ/サケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ・へこみ	P	色あせ/サケ	G	ガラスキズ																	
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																	
内装スレ			登録No. _____ 名義中																							
ステアリングスレ			月 _____ 日 _____ までに名義できる方																							
シリアル No.			JF1-1210657																							
FW	トピ石	備A	ワレ	外装	小	ホイル	エアロ	シリアル No.																		
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	⑨	長さ cm	幅 cm																	
								高さ cm	最大積重量 kg																	