


2013 Honda N-BOX G SS Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF1	DISPLACEMENT 658 cc		
YEAR / REG. 2013/11	MILEAGE 49,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. JF1-1315728	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels Navigation System		Power Sliding Doors (Both Sides) (Both...	
INSPECTOR REPORT			
Interior has light dirt and scuffs. Left power window is faulty. Wheels show minor scratches. Exterior has minor paint imperfections (TP), one scratch on the front glass, and numerous other scratches. The exterior has been repainted. Mechanical key is missing.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/11月	メーカー ホンダ	ドア数 5	ボディ形状 軽四	評価点 4
車名 N-BOX	グレード GSSパッケージ	駆動方式 2WD	4WD	
車種 軽自動車・その他 ()	排気量 660 cc	型式 DBA-JF1	通称 軽	内装 A・B・C
年 -	月 -	日 -	色 シルバー	ディーゼル
走行 49,000 km	インパネ	AT	後日進品 (保証書・取扱説明書等)	
外装色 シルバー	カラーNo. ()	エアコン AC・AG・WAG ()	装備品のみ O印 を記入	
内装色 ()	乗車定員 4人	サンルーフ	革シート	
左・右 左・右	ディーラー -	走行 -	ナビゲーション	9,790円
セールスポイント スマートキー 両Pスラ メモリーナビ Bカメラ レベライザー ウインカーミラー 純正AW				
検査記入欄 内装汚れ・スレ ドア開閉不良 ホイール 片側ドア ガラス割傷 メカニカルキー欠損 外装色剥離 外装腐蝕	修復歴 有・無 A サイズ U ヘッドライト B キズ・ヘコ D 車体色・ボディ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 YX 交換済			
名義中 月 日 までに名義できる方				車体 No. JF1-1315728
内装 シロ	外装 シルバー	小 Q・Q	ホイール Q・Q	エアロ Q・Q
内装 シロ	外装 シルバー	小 Q・Q	ホイール Q・Q	エアロ Q・Q