

2013 Honda N BOX G Turbo Package		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JF1	DISPLACEMENT 658 cc		
YEAR / REG. 2013/04	MILEAGE 136,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Kei		
CHASSIS NO. JF1-2107813	DIMENSIONS (L X W X H) 340 × 148 × 178 cm		
SALES POINTS			
Alloy Wheels		Leather Seats	
Power Sliding Doors (Both Sides) (Both...		Cruise Control	
Navigation System			
INSPECTOR REPORT			
1 remote key, steering wheel wear (A), seat wear and sagging (A), interior trim wear and stains (A), minor body scratches (A), mirror scratches (A), wheel scratches (A), underbody rust (S), power window stone chip, interior dirt and wear.			

ORIGINAL JAPANESE AUCTION SHEET

H25/4月	ホンダ	5	軽四	3.5			
N-BOX		G・ターボパッケージ		4WD			
車種	白車用・その他 ()	排気量	650 cc	型式	DBA-JF1	内装	A・B・C
年式	10年	4月	扶養	燃料	ガソリン	ディーゼル	
走行	136,000 km	メイル	AT	後日選り品 (保証書・取扱説明書等)			
外装色	ブラック	カラーNo.	0	エアコン	AG・AC・WAG ()	装備品のみ・O印を記入	
内装色	その他	乗車定員	4人	PS	ABS	ナビ	サンルーフ
左・右	左	ディーラー	直付	9,790円	販売額	ABS	ナビ
セールスポイント				修復歴			
ディスチャージヘッドライト<HID> クルーズコントロール ナビ装着用スペシャルパッケージ 本革巻 ガーニッシュ付ステアリングホイール 14インチアルミホイール パドルシフト				修復歴			
検査記入欄				修復歴			
A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損				修復歴			
JF1-2107813				修復歴			
修復歴				修復歴			