


2013 Honda N-ONE 660 G L Package		OVERALL R	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-JG1	DISPLACEMENT 658 cc		
YEAR / REG. 2013/03	MILEAGE 70,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Hatchback		
CHASSIS NO. JG1-1036326	DIMENSIONS (L X W X H) 340 × 148 × 161 cm		
INSPECTOR REPORT			
Headliner and seats have stains and scuffs. Front inner cross support and lower support are damaged (XX). Body panel/bumper damage (BP).			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/3月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 R
車名 N-ONE	グレード 660 GLパッケージイモ ビライザー 電格ミラー	駆動区分 2WD 4WD	内装 A・B・C	
車歴 自家用・その他()	排気量 660 cc	型式 DBA-JG1	通称 型式	
車検 -年-月/日	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書等)	
走行 70,000 km	マイル インパネ CVT	シフト ハイブリッド		
外装色 レッドII	カラーNo. ()	エアコン (A)・AAG・WAG・()	整備品のみ O印 を記入	
内装色 ()	乗車定員 4人	PS	AW	サンルーフ
ハンド 左・右	輸入 ディーラー	リサイクル料 9,670円・預託無	エディック	ナビ
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エ アバック/カーテンエアバック/アイドリングストップ/ス マートキー/盗難防止システム/H I D ・キセノン・ディ スチャージ/横滑り防止装置 (E S C) /ベンチシート/CD				
修復歴 0. 無				
検査記入欄 天張り、シートしみスレ Fインナー・コササポート、ロアサポート××・BP	A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・剥け G ガラスキズ W 補修跡 S サビ C 腐食 X 交換箇所 XX 交換車 登録No. 月 日 までに名義できる方 車体 番号 JG1-1036326 シリアル No.			
PW トド石	備A	フレ	外装 小 A・U ホイール A・曲 エアロ A・フレ	シリアル No.
内装 ヨコシ	シミ	ヤブレ	コゲ	コゲ穴
			オーディ穴	スレ
長さ cm	幅 cm	高さ cm	最大積載量 Kg	