

2013 Honda N-ONE Premium 660 Premium		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JG1	DISPLACEMENT 658 cc		
YEAR / REG. 2013/03	MILEAGE 81,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. JG1-1034171	DIMENSIONS (L X W X H) 340 × 148 × 161 cm		
SALES POINTS			
Alloy Wheels		Back Camera	
INSPECTOR REPORT			
Underbody undercoat painted, some rust. Minor repair marks, minor exterior scratches/dents. Rear wiper missing. Some stains/scratches inside the cabin.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H25 / 3月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4					
車名 N-ONE	グレード 660 プレミアム HIDLED フォグドラレコディスプレイオーディオBモニター	駆動方式 4WD	4WD						
車種 自家用・その他 ()	排気量 660 cc	型式 DBA-JG1	通称 4WD	内装 A・B・C					
燃料 ハイブリッド ()	シフト CVT	走行 81,000 km							
外装色 プレミアムブルー-ムーンパールパー-ム	カラーNo. ()	エアコン ()	4人	装備品のみ ORP を記入					
左・右 ()	ディーラー ()	走行 ()	9,670円	エプロン ()					
セールスポイント									
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/ワンセグTV/ETC/アイドリングストップ/スマートキー/H I D・キセノン・ディスチャージ機滑り防止装置 (E S C) /ベンチシート/D V D再生/C D/バックカメラ/定期点検記録簿									
検査記入欄									
下廻りアンダーコート塗装、一部錆 補修跡有り、外装傷凹み少 リアワイパー欠品 ルーム内一部汚れ僅									
修理履歴									
有・無									
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
登録No.					月 日				
車体番号					JG1-1034171				
FW	トビ	傷A	フレ	外装	小	ホイール	エアロ	シリアルNo.	
内装	ゴキ	シミ	ヤブレ	コガ	コガ	オーディオ	CD	長さ	幅
					重量	cm	高さ	cm	最大積載量
					Kg				