

2013 Honda N-ONE Premium 660 Premium L Package		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-JG1	DISPLACEMENT 658 cc		
YEAR / REG. 2013/01	MILEAGE 99,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE Hatchback		
CHASSIS NO. JG1-1008784	DIMENSIONS (L X W X H) 340 × 148 × 161 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Trunk floor dent, mirror replaced, interior dirt and scratches, steering wheel scuff, minor headliner dirt, minor exterior scratches.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25 / 1月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 R
車名 N-ONE	グレード 660 プレミアム L パッケージ	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 660 CC	型式 DBA-JG1	通称 型式	内装 A・B
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	検出過剰品 (保証書・取扱説明書 等)	
走行 99,000 km	シフト インパネ	CVT		
外装色 プレミアムブルーメーン・パール	カラーNo. ()	エアコン	装備品のみ O印 を記入	
()	内装色 ()	4人	サンルーフ	
左・右 左・右	ディーラー	走行	9,670円	エレクトロニクス
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/カーテンエアバック/アイドリングストップ/スマートキー/盗難防止システム/H I D ・キセノン・ディスタンスチャージ/横滑り防止装置 (E S C) /ベンチシート/C D				
検査記入欄				
トランクフロアW				
ミラーx				
室内汚れ傷				
ハンドル握れ				
天板リコグ小汚れ				
外装小傷				
A キズ U ヘッドライト B キズ・ヘッド P 色あせ・ボケ Q ガラスキズ				
W 補修跡 S サビ C 腐食 X 交換済 XX 交換済				
登録No. 月 日 までにも変更できる方				
車体番号 JG1-1008784				
シリアル No.				
FW トビ石 傷A フレ 外装 小 A・U A・曲 A・フレ	長さ cm 幅 cm 高さ cm 最大積載量 Kg			
内装 300 シス ヤブレ 300 コガク オーディオ穴 スレ				