

2013 Honda ODYSSEY Absolute		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE RC1	DISPLACEMENT 2,356 cc		
YEAR / REG. 2013/10	MILEAGE 130,184 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. RC1-1000978	DIMENSIONS (L X W X H) 483 × 182 × 169 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Pre-Collision Braking Navigation System	
INSPECTOR REPORT			
Right front dashboard distortion, light interior stains.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H25/10月	メーカー ホンダ	ドア枚数 5	ボディ形状 ミニバン/ワンボックス	評価値 R
車名 オデッセイ	グレード アブソルート	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 2400 cc	型式 RC1	通称 内装	A・B・C
年 -	月 -	日 -	燃料 ガソリン	ディーゼル
走行 130,184 km	インパネ	AT	後付選り品 (保証書・取扱説明書等)	
外装色 プレミアムヴィーナスブラックパール	カラーNo. ()	エアコン A・A・G・W・A・G ()	装備品のみ O印 を記入	
内装色 ()	乗車定員 7人	サンルーフ	革シート	
左・前・右 左・前・右	ディーラー ディーラー	走行 走行	リサイクル料 14,420円	預託金 エブリック
セールスポイント				
3列シート/CD/ウォークスルー/バックカメラ/ETC/横滑り防止装置 (ESC)/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビ他/フルセグTV/衝突被害軽減ブレーキ/衝突安全ボディ/アイドリングストップ/オートクルーズコントロール/オートマン/DVD再生/両側電動スライドドア				
検査記入欄				
右インパネ歪み 室内薄汚れ				
修理歴 G・無				
A キズ U ヘビイサレ B キズ+ヘビイ P 色あせ+サケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換済				
登録No. 月 日 までに名義できる方				
車体番号 RC1-1000978				
FW トピ石 備A フレ 外装 小 A・U ホイル A・曲 エアロ シリアル No.				
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ				
車種 長さ cm 幅 cm 高さ cm 最大積重量 kg				